


Step 4/4 • Schritt 4/4



Peel off mask 2 after the application is completed.

Entfernen Sie Abdeckung 2 nach dem Anbringen der Schutzfolie.



© 2013 Jöllenbeck GmbH.

All rights reserved. SPEEDLINK®, the SPEEDLINK word mark and the SPEEDLINK swoosh are registered trademarks of Jöllenbeck GmbH. Jöllenbeck GmbH shall not be made liable for any errors that may appear in this manual. Information contained herein is subject to change without prior notice.

All trademarks are the property of their respective owner. Please keep this information in a safe place for later reference.

JÖLLENBECK GmbH, Kreuzberg 2
27404 Weertzen, GERMANY

● ● ● www.speedlink.com ● ● ●


SL-5351-01
V1.0



Applying the
Screen Protection
Anbringen der
Schutzfolie




Step 1/4 • Schritt 1/4



Please note that the protective film (D) is enclosed by two masks (1+2).

Bitte beachten Sie, dass die Schutzfolie (D) von zwei Abdeckungen umschlossen ist.


Step 2/4 • Schritt 2/4



Peel off mask 1 carefully and take care not to touch the adhesive side.

Entfernen Sie vorsichtig Abdeckung 1 und berühren Sie hierbei nicht die Klebeseite.

Step 3/4 • Schritt 3/4



Align the protective film (D) with the edges of the screen and plane it with the applicator.

Richten Sie die Schutzfolie (D) an den Ecken des Displays aus und streichen Sie sie mit dem Folienwerkzeug glatt.

D = Protective film / Schutzfolie, 1 + 2 = Protection masks / Abdeckungen